Laser Safety Audits Of Research Labs



Johnny Jones

Laser-Professionals Inc.

Planning the Audit

- Write an objective statement.
- Create a data form that meets your needs.
- ** Ask all personnel about training.
- Make sketches of labs; take photos.
- Train audit team?

OPEN BEAM CONTROL MEASURES

ANSI Section 4.3.1.1

- **#** Training
- Beam Control
- ****** Laser Safety Eyewear
- ***** Written Procedures
- ****** Laser Controlled Area

First Question for the LSO: Have Training Requirements Been Met?

- ** Review Laser Safety Officer training.
- ** Review training records for laser personnel.
- * Ask all personnel about training.

First Question In Every Lab: Where is the greatest hazard?

- ***** Ignore entryway and interlocks in the beginning.
- ** Ask laser personnel to explain the setup, the hazards, and the controls.
- ** Review Written Procedures and SOPs.
- ***** Evaluate Beam Control.
- * Ask what could go wrong?


EXAMPLES OF GOOD BEAM CONTROL











CURBS ON OPTICAL TABLE




COMPUTERS IN RESEARCH LABS








Allowing a direct view from a computer workstation into a laser experimental setup increases the risk of eye exposure to reflected beams.





















TUNABLE ULTRASHORT PULSE SYSTEM




TI:SAPPHIRE ULTRASHORT PULSE SYSTEM



LASER SAFETY EYEWEAR




EYEWEAR LABELS



All eyewear must be labeled!


PLASTIC EYEWEAR CHARACTERISTICS



BEAM VIEWING DEVICES








WHO HAS PRIMARY RESPONSIBLITY FOR LASER SAFETY ANY TIME A CLASS 3B OR CLASS 4 LASER IS OPERATED?

The person operating the laser always has the primary responsibility for all hazards associated with laser use.

Ask About Hazards During Alignment



SAFE BEAM ALIGNMENT

- Most beam injuries occur during alignment.
- Only trained personnel may align class 3B or class 4 lasers (<u>NO EXCEPTIONS!</u>)
- Laser safety eyewear is required for class 3B and class 4 beam alignment.
- ANSI <u>REQUIRES</u> approved, written alignment procedures for <u>ALL</u> class 4 laser alignment activities and recommends them for class 3B.

LASER PROTECTIVE BARRIERS









CLASS 4 ENTRYWAY CONTROLS

Section 4.3.10.2.2

- 1. Non-Defeatable Entryway Controls
 - Doorway interlock is non-defeatable
 - Training of authorized users only
- 2. Defeatable Entryway Controls
 - Doorway interlock is defeatable
 - Training of all personnel with access
 - Barrier and eyewear at door
- 3. Procedural Entryway Controls
 - No doorway interlock
 - Training of all personnel with access
 - Barrier and eyewear at door
 - Visible or audible signal at doorway




LABORATORY DOOR INTERLOCK



ENTRYWAY WARNING LIGHTS



A DANGER



VISIBLE and/ or INVISIBLE LASER RADIATION-AVOID EYE OR SKIN EXPOSURE TO DIRECT OR SCATTERED RADIATION.

ND:YAG 1064 nm 100 Watts Max. Average Power Eyewear Required: OD ≥ 5 @ 1064 nm

CLASS 4 LASER

Finish the Audit

- * Send an audit report to all laser owners.
- * Write a final audit report.
- Recommend improvements.

Experience Makes the Difference